

FEDERAL ENERGY REGULATORY COMMISSION
Office of Energy Projects
Division of Dam Safety and Inspections – Atlanta Regional Office

October 14, 2025

In reply refer to:
P-516 Saluda

VIA Electronic Mail

Ms. Iris Griffin
Vice President-Power Generation
Dominion Energy South Carolina, Inc. (DESC)
Iris.Griffin@dominionenergy.com

Subject: Public Safety Incident – Capsized Boat in Temporary Boater Exclusion Zone

Dear Ms. Griffin:

Mr. Ray Ammarell's July 31, 2025, submittal reported information regarding a public safety incident at the Saluda Project No. 516. The incident involved a capsized boat that floated into a temporary boater exclusion zone near the intake towers. The exclusion zone is in place for the ongoing headgates replacement project. Mr. Ammarell provided an initial notification of the incident on July 22, 2025, via email.

We have completed our review and found your report and initial notification satisfy the Commission's 18 CFR § 12.10 reporting requirements.

We appreciate your continued cooperation in ensuring the safety of your project. If you have any questions, please contact Mr. Shae Hoschek at (678) 245-3077 or by e-mail at shae.hoschek@ferc.gov.

Sincerely,

William J. Brown, P.E.
Regional Engineer

Cc: VIA Electronic Mail

Mr. Ray Ammarell, P.E.
Manager-Dam Safety and Civil Engineering
Chief Dam Safety Engineer
Dominion Energy South Carolina, Inc.
Raymond.Ammarell@dominionenergy.com